

Green Lake County's Inspection Report

1. Type of Inspection (check all that apply) Annual Major Storm Site
2. Date of Inspection: 11/07/2022
3. Drainage District Name or Number: District 5
4. Location of Damage or Complaint:
(Attach USDA Farm Service Agency aerial photo with site identified in red)
5. Name of person(s) making complaint or accompanying the inspection:
Dick Sobieski had spoken with John Trochinski about his concerns with tile blowouts.
Stopped by house and nobody was around.
6. Description of Damage (attach additional sheets if needed):
Could not see any damaged areas. The driveway culverts were replaced with road construction, and it looks like the ditch was reshaped and seeded. There may be a few low spots in final grading that could be repaired.
7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):
None at this time.

8. Inspector(s):

Print Name: Richard M Sobieski

Todd Morris – Land Conservation Dept.

Signature: _____

Green Lake County's Inspection Report

9. Type of Inspection (check all that apply) Annual Major Storm Site

10. Date of Inspection: 11/07/2022

11. Drainage District Name or Number: Seneca-Warren

12. Location of Damage or Complaint:

(Attach USDA Farm Service Agency aerial photo with site identified in red)

13. Name of person(s) making complaint or accompanying the inspection:

Spoke with Rodney Zietlow on the phone, he had concerns that ditch east of his house is backing up when flowing into the Town Drain and also feels that the center of the ditch is in need of some maintenance cleaning.

14. Description of Damage (attach additional sheets if needed):

During inspection there are areas that have brush growing along the ditch that needs to be removed. Also past surveys have shown that the ditch bottom is 1.0' – 1.5' high and could be lowered to meet design specs. Also some of the culverts were never lowered to design specs and this is also keeping the bottom about 1.5' higher than design specs.

15. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

Clean out center of ditch, do not touch sides, starting on DNR property at South Rd and work way to the north up to Hwy F. Remove/cut brush and treat stumps to prevent regrowth of box elder and buckthorn. Leo Souder would also like to clean the section of ditch west of Hwy EE, he will clean it at his cost and remove the brush from this area.

16. Inspector(s):

Print Name: Richard M Sobieski

Todd Morris – Land Conservation Dept.

Signature: _____